



Power Out
 2x 16 pin
 box connectors
 to busses

Status
 LEDs
 $R1 = 470R$
 $R2, R3 = 1K$

Resettable
 Fuses
 $F1 = 500mA$
 $F2, F3 = 1.1A$

Power In
 from
 Meanwell
 RT65B

